DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 1.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-013942 Address: 333 Burma Road **Date Inspected:** 11-May-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1330 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: American Bridge/Fluor Enterprises, a JV **Location:** Job Site

CWI Name: N/A**CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A

N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** Orthotropic Box Girders

Summary of Items Observed:

The Quality Assurance Inspector (QAI), Scott Croff, was present at the Self Anchored Span (SAS) job site to observe the scheduled fabrication and welding of components for the SFOBB project.

The QAI observed ABF activities at the Pier 7 location. The QAI did not observe any Quality Control (QC) Inspectors present. The QAI noted that ABF personnel are setting construction equipment into the OBG segment 5W and grinding the base metal edges to prep the field splice welding. The QAI noted that ABF personnel are welding on barges and job related equipment. The QAI also noted that the contractor is assembling parts of the temporary trestle on the barges at Pier 7. The QAI did not observe any personnel welding on bridge components. The QAI noted that this work was in progress until the end of the shift. The QAI was informed that the receiving inspection for OBG segment 6W will be performed tomorrow, 5-12-2010. The QAI noted that there are still temporary shipping braces visible inside the OBG segment.

The QAI reviewed contract related documents including the submitted and approved Welding Quality Control Plan (WQCP) and approved revisions to the WQCP and newly issued ABFJV non-conformance reports. The QAI updated the records of the non-conforming incident reports and also the contractor's submitted requests for information. The QAI continued reviewing the contractor's submitted welding reports, submittal # 1536 Revision 4. The review was in progress at the end of this shift.

Summary of Conversations:

The QAI had general conversations with ABF and Caltrans personnel during this shift. Except as described above, there were no other notable conversations or observations.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mohammad Fatemi, (916)813-3677, who represents the Office of Structural Materials for your project.

Inspected By:	Croff,Scott	Quality Assurance Inspector
Reviewed By:	Levell,Bill	QA Reviewer